

These articles and information is brought to you by The 1937 and 1938 Buicks Club. For more information please contact us at:

http://autos.groups.yahoo.com/group/1937and1938Buicks/ or WWW.1937and1938Buicks.com

-- Warning Notice --

It the mission and goal of 1937 and 1938 Buicks Club is to provide information, helpful hints, advice, directions and reference information for the repair, maintenance, authentic restoration and knowledge development in regards to 1937 and 1938 Buick's. Content is offered as informational only.

The 1937 and 1938 Buicks Club does not knowingly accept false or misleading content or advertising. Nor does The 1937 and 1938 Buicks Club assume any responsibility for the consequences that may occur should any such material appear.

The 1937 and 1938 Buicks Club does not guarantee the quality of any information which is included in this or any other publication. Under no circumstances shall The 1937 and 1938 Buicks Club be liable for any damages, losses, or injuries resulting from use reliance on the content of this or any other publication. Any reliance on this or any other publication content is at your own risk.

As a precautionary measure, The 1937 and 1938 Buicks Club strongly recommends that you contact a professional mechanic or restoration shop to check your work or answer specific questions.


-- Copyright Notice --

All rights reserved. All documents and publications on The 1937 and 1938 Buicks Club web site or that can be down loaded from The 1937 and 1938 Buicks Club web site are protected under both U.S. Federal copyright law and international treaties. No component of this site, including text, images and computer code, may not be reproduced or copied in any form or by any means--electronic, graphic, digital or mechanical, including photocopying or information storage & retrieval systems--without the express prior written permission of The 1937 and 1938 Buicks Club.

TORQUE-TUBE

THE NEWS PUBLICATION FOR MEMBERS

OF THE 1937-1938 BUICK CLUB • FOUNDED 1980



Volume IV · Number 3

• FOUNDED BY DAVE LEWIS •



THE TORQUE-TUBE THE NEWS PUBLICATION FOR MEMBERS OF THE 1937-1938 BUICK CLUB - FOUNDED 1980



VOL. IV • December 1985 • NO. 3

Believe it or not, I cannot think of a great deal to say in the way of introductory matter, except that, due to the talent and effort of a FEW dedicated members, we have some GREAT STUFF in this issue. However, that does not mean that the rest of you are off the hook. For that rest, the HARANGUE & DIATRIBE are still in effect, and are incorporated herein by reference as though fully set forth. (How's that for a little legalese?) Beyond that, and my annual reminder not to give your wife a floor jack for Christmas...

Happy Holidays, Friends.



COVER: Just Kidding, Folks. See Page 18.

- William E. Olson, Editor •
- 842 Mission Hills Lane, Worthington, Ohio 43085 •



NEW MEMBERS



Robert G. Lusby (#544) 2241 Sylvania Ave. Knoxville, TN 37920 615/573-8708 '38 46S

Jim Woolsey(#545) 1219 Roosevelt Escondido, CA 92027 '38 61

Clarence Hoffman (#546) 3015 Chatham Cleveland, OH 44113 216/281-8343 138 668

Ed Wall (#547) 4282 Country Squire Ln. Fairfax, VA 22032 703/425-9852

Daniel Cooke (#548) 29 Daventry Ct. Lynnfield, MA 01940 617/334-4806 '38 41 Jimmie Hair (#549) P.O.Box 685 Dalton, GA 30720 404/278-6970 '37 41

Joseph L.DiPietro, Jr.(#550) 301 S.Rollins Rd. Springfield, PA 19064 215/544-2242

Emmett Lyman (#551) Town St. East Haddam, CT 06423 203/873-9715 '38 41 '37 60C

Joseph J. Jacobs (#552) Tuckahoe Rd. Milmay, NJ 08340 609/691-6779

Bill Evans (#553) 111 South Corbin Holly, MI 48442 Curt Brohard (#554) 1084 Gardenia Terrace Alameda, CA 94501 415/521-4299

Donald Teal (#555) 1923 64th Ave. N. St.Petersburg, FL 33702 813/527-9602

Robert Sanzotera (#556) ABCL Jubail Box R APO New York 09616-5379 '37 67 (permanent home: Lubbock, TX)

William VanderHoven (#557) RR 3, 5170 92nd Rd. Newaygo, MI 49337 '38 46

Jose G. Pardo (#558) A.A. 7793 Cali COLOMBIA, SOUTH AMERICA '37 68

Dan Howell (#559) 1298 Trojan Ave. San Leandro, CA 94579 415/357-8989






From Australia





Ron Woods (#528) of Port Macquarie, New South Wales sent me this shot of his 1937 Holden Century, decked out with ribbons in a parade of white cars. What's the car behind?



Here we have some photos of a very remarkable automobile, Dr. Neal Gapoff's custom-bodied 1937 town car. Neal (#526), a chiropractor in Marin County, California, says he heard about the car when he ran into a friend at an auction. At that time -- January 1985 -- the car was in Europe, where it had presumably spent all of its life before Neal negotiated its purchase and shipment to California. Neal knows nothing of its history, but it is assumed that it was one of very few chassis-and-cowl units exported in 1937. The body is by Franay, a firm about which I am totally ignorant, and appears to be built on an 80-series chassis.

Several things are worthy of note. First, the headlights have been exchanged for the typical English-style lamps of the 1930's and 40's. (See, for example, the cars made for the Duke of Windsor and other worthies pictured in The Buick - a Complete History; for some reason the Limeys could not tolerate U.S. lights.) However, the car has left-hand drive, which may indicate it was not made as an export model, or that it was originally intended for use in Continental Europe, not the British Isles. You can also see that the taillights (which I think are the least successful part of the design) are angled upward, and that the doors are hung on the center pillar. The roof over the chauffeur's compartment may be removed. The interior, which looks -- but may not be -- original, is a light tannish color with black or dark blue piping. Wood trim appears to be Brazilian rosewood. The sharp-eyed among you will also have observed that the steering wheel is 1938.


All in all, this is perhaps the best-looking formal custom body I have seen on a pre-War Buick. The Brewster cars, by contrast, have, to my eye, a funky, awkward look that is half late-thirties and half late-twenties. With possible exception of the taillights and a few other little details, the Franay car is a dignified, well-integrated design, quite suitable for stately progress from shop to shop or from city club to opera.


I expect that in Europe, rolling around in a custom Buick in those days would have had a certain cachet, rather like having a Volvo 760 or a Jaguar in the U.S. today. After all, no less a personage than the Prince of Wales had shown the way in 1936 when he ordered two special McLaughlin Limiteds. And Neal says the car, now returned to the U.S., is a real show stopper here. He would like to know more about the car's history and the Franay firm. If any member can help out with some information or leads, please let me know.



(CONTINUED)









Matching 1937 Colors

In the following several pages, we present what I think is one of the most significant achievements of this Club to date: a complete guide to duplicating all of the paint colors used on 1937 Buick automobiles. The formulas have been developed over a period of time by Lauren Matley (#049), who has a paint business in Seattle with some very sophisticated, state-of-the-art equipment. All these formulas employ DuPont products, and through their use any restorer can go to any of the **6000** DuPont auto paint jobbers nationwide and get a custom-mixed paint to match any of the 12 body colors offered by Buick in 1937, plus the "engine green." With a few exceptions, formulas for both lacquer and enamel have been developed.

This has been a major undertaking by Lauren, and I cannot overstate either the difficulty of the work or its value to all of us. We are indebted to him, and I have already expressed to Lauren our gratitude. (Incidentally, Lauren has a magnificent 1937 Special convertible sedan, which was restored with painstaking thoroughness, and which was pictured several issues back.)

This presentation begins with an article describing generally the evolution of auto paints, the problems encountered in trying to duplicate 50-year old paint formulas today, and the process Lauren has used to do that. This article, although it carries Lauren's "by-line," is actually the result of my combining and editing the substance of several letters he sent to me over the past several months. Accordingly, Lauren deserves credit for all the good stuff in it, but if there are any mistakes or ambiguities, those are entirely my fault, and will be corrected if need be.

At the outset, an important word of caution: the formulas will produce colors that, in Lauren's judgment, are as close to the original colors as it is reasonably possible to come; however, they may not be -- indeed, probably are not -- precise duplications of the factory-fresh cars. The matches have been made using some of the very best technology available, from a set of original samples that are probably the most accurate obtainable today. Of necessity, however, the process has in it a considerable amount of Lauren's personal judgments and perceptions, and even those excellent samples, however well-preserved, may not themselves be precise. While I have the highest regard for Lauren's knowledge and experience in the field of automotive finishes, every person's perception of color may vary to a greater or lesser extent from every other person's. Moreover, all colored finishes change to some degree over time. Therefore, if you have a 1937 car still in its original paint, it is quite likely that use of the applicable formula will produce a color different in appearance from that now on the car. This is not because the formula is poor, but rather because the car's paint will have changed color over time, even in areas protected from weather. Likewise, you may have seen a refinished car whose owner claimed to have matched the original color, and find that the appropriate formula does not appear to give a close match of that car. There are several reasons, of course, why this might be so. As noted above, we believe we have come as close as is humanly possible.

SETTING YOU STRAIGHT ON OLDER CAR COLORS AND FORMULATIONS

by Lauren Matley

All paint companies over the years have reformulated, added advanced technology in existing mixing-color bases, eliminated entire product lines and added new product lines within the mixing systems; this process has created many obsolete formulas. Formulas that were popular for fleets, or that covered a wide range of marques for several years, were the only ones salvaged through updating into the newer products. As technology has advanced again and again, very few formulas have been carried over to this day from the past.

DuPont "Duco" introcellulose lacquer was invented in 1923, reformulated four times through 1954, and replaced by "Lucite" acrylic lacquer, which itself has been reformulated six times through 1982. "Dulux" enamel was first marketed in 1929, and reformulated four times through 1965; "Centari" acrylic enamel was added in 1969 and reformulated three times through 1981; "Imron" polyurethane enamel was added in 1970. Twelve to 22 new colors are added annually per automobile marque. As you can imagine, DuPont would not want to go back through the 18,000 formulas that currently exist and reformulate color mixes for cars that exist today only in very small numbers. There would be no return on the lab cost.

By now I think you can start to understand why formulas for automotive colors are not permanent. A formula for a color -- say, Sandringham Maroon for a 1937 Buick -- may be resurrected, but all the mixing colors on that formula card would be obsolete and unavailable, rendering that color formula effectively useless.

Metallic colors illustrate this especially well. Early in their development, the flake grind was extra fine, fine and medium. Technological advances in resins permitted flashier colors with greater durability, and the grinds used today are medium coarse, extra coarse, brilliant and extra brilliant, made from aluminum and mylar base products. In the thirties metallic colors were a new development in glamourizing the automobile, durability of clear dispersion resins was very very poor, ground aluminum pigments were dispersed in very opaque colors which tends to mute the metallic effect, plus the grind or size of these metallic pigments was extremely fine by today's standards. In order to duplicate these metallic colors, modern aluminum grinds must be blended with transparent whites to simulate not only the muted metallic effect, but to simulate the fine aluminum flake grinds of the 1930's. Today's paint technology allows metallics to be dispersed in clears at a 20 to 1 ratio since today's clear resin products are more durable than the highly-pigmented colors of just a few years ago, and thus tend to be very brilliant.

How can antique car colors be duplicated today? We can, and do, improvise formulas to meet the needs. [Editor's Note: by "we," Laruen means his firm, Auto Body Color Supply, Inc. -- address appears below.] Our approach is the use of a tool called a color map, developed by Sikkens of the Netherlands. The color map consists of thousands of colors arranged first in families, then by shade and hue and from pale to dark in tones. Each "chip" is an actual sprayed unit, and each has a 3/8-inch hole in the center to make direct comparsions to other color samples. The chips are arranged in numbered columns and rows by number and letter. An index lists the number/letter combination identifying a particular chip location, and then gives the corresponding formula, formulas, or make/model/code number to mix the color selected as the match. This is the most foolproof of systems when coupled with a color-corrected light box for making the comparison. Our particular expertise has been color development for large fleets, major manufacturers, airlines, body builders, and yes, even old car nuts. We use the color map/light box system

7

as a starting point, then develop special exact color matches (if required), or direct simulated matches from the color map. The latter has proven very successful for antique car restorers' needs, and we do a creditable job on those needs.

I have developed all the 1937 Buick colors using a great set of 3 \times 6 mint factory standards as a reference. If I had a comparable set of 1938 Buick color standards I could easily develop all the 1938 colors as well. I have both acrylic enamel and lacquer formulas for most of the 1937 colors.

My solutions, although not complete, start with using the original DuPont prefix codes, 246 for non-metallic lacquer, 202 for metallic lacquer, 93 for non-metallic enamel, and 181 for metallic enamel, the enamel codes modified with a "U" for urethane. The line codes are in parentheses to indicate we are using the original numerical system for the original DuPont color with a modern product suffix letter to denote acrylic lacquer from acrylic enamel and polywrethane. For example code 501, Chancellor Blue, shows an original DuPont numerical code for "DUCO" nitrocellulose lacquer of 246 - 1267 and our update formulas use the number (246)-1267-LH for acrylic lacquer. This will assist

in cross-referenced numbers in double checking the correct color from other formula listings, etc. However, these new code numbers are my own more-or-less arbitrary creations, and are for reference purposes only. Paint cannot be mixed from them alone, as they will mean nothing to a paint supplier. You must give the supplier the formula for the color you want. You will note not all types of finishes have been developed; formulation takes time and the offerings here cover all but one color in acrylic lacquer and most colors in acrylic enamel. This should solve any color problem for most 1937 restoration projects. Members can take the formulas to any one of the 6000 DuPont jobbers nationwide and get color mixed.

I hope this information helps clear the air on color formulas for antique cars. Only a handful of colors have continued in use from the 1930's -- mostly GM and Ford truck colors -- but we have no problem finding solutions to color problems: that's our main line of business.



SUPPLY INC.

13437 1st Ave. So.

Seattle, WA 98168

(206) 246-6600



IMPORTANT NOTES ON THE FORMULAS

- (1) Where an asterisk (*) is used with a lacquer formula, if you intend to apply a top coat of 380-S Clear, substitute 475-L Binder in place of 465-L Binder and 485-L Balancer.
- (2) The formula given for Samarra Beige (No. 508) will produce a non-metallic finish. I have seen Samarra Beige described as a metallic color on old DuPont and other paint charts. It may be that the formula was changed during the model year. If you wish to paint your car a metallic Samarra Beige, please consult Lauren Matley or your paint supplier.
- (3) There were two 1937 Hampton Greys, Code No. 510 and Code No. 512. It is assumed that this color was changed during the model year. We give the formula for No. 510, since Lauren does not have a sample of No. 512. If you have a 512 car and wish to repaint, either use the 510 formula, or invent something. If any member has information on the difference between 510 and 512, please write or call the Editor.
- (4) Except where noted, enamel formulas are for DuPont CENTARI acrylic enamel and lacquer formulas are for DuPont LUCITE acrylic lacquer. IMRON is a polyurethane enamel, highly recommended for engine and frames.
- (5) For a black car (Code 500 Imperial Black, 1937) use any of the following, available in factory package quarts and gallons:

DUCO Nitrocellulose Lacquer - 44 LUCITE Acrylic Lacquer - 99 CENTARI Acrylic Enamel - 99A IMRON Polywrethane Enamel - 99U


(DUCO, DULUX, LUCITE, CENTARI, IMRON are DuPont registered trademarks.)

(6) The number shown opposite the various mixing colors are "Scale Settings" which the paint supplier will use in making up the paint. Unless otherwise noted, these are for one gallon.

Lode 500 - Imperial Black - see Note(5) Cade 501 - Chancellor Blue Enamel (93) 1267 AH Lacquer (246) 1267 LiH 758-5 Drier 177 440-L Violet 20 747-A MonRed 206 415-L Violet 48 700-A White 247 401-L White 176 741-A Yellow Green 777 406-L Black 472 705-A Black 1483 417-L Blue 1168 721-A Blue 2425 465-L Binder 2288 756-A Binder 3556 485-L Balancer 3472

Code 502 - Coronary	Treen
Enamel (93) 51252 AH	Lacquer (296) 51252 LH
758-5 Drier 178 724-A Blue 177 701-A White 987 741-A Yellow Green 2059 705-A Black 3562	418-L Blue 44 401-L White 256 406-L Black 636 425-L Green 1400 465-L Binder 3276 485-L Balancer 3540
Code 503 - Sundringh	am Maroon
Enamel - "IMRON"	Lacquer *(246) 50721LH
535-U Black 410 553-U Violet 810 557-U Red 900 536-U Oxide 920 (NOTE: Settings are for QUART)	405-L Black 876 441-L Dark Violet 1674 406-L Black 2000 465-L Binder 3350 485-L Balancer 3670
Code 504 - Sudan Blue	(Metallic)
Enamel (181) 51576 AH	Lacquer * (202) 515672H
758-5 Drier 176 797-A MonRed 293 705-A Black 1030 724-A Blue 1796 722-A Phthalo Blue 2486 710-A Med. Alum. 3595	430-L MonRed 16 406-L Black 202 411-L Med. Alum. 490 418-L Lt. Blue 786 419-L Organic Blue 1406 465-L Binder 3184 485-L Balancer 3484
Code 505 - Wellington	(Erey (Metallie)
Enume 1 (181) 51576 AH	Lacquer
758-5 Drien 178 747-A Mon Red 203 701-A White 231 710-A Alum. Med. 1207 705-A Black 3556	No formula
Code 506 - Windsor Er	ey (Metallic)
Ename/ (181) 51771 AH	Lacquer * (202) 51771 LH
758-5 Drier 117 723-A Violet 201 721-A Blue 304 710-A Alum Med. 908 705-A Black 2147 756-A Binder 3596	455-L Eold 20 401-L White 56 492-L Blue 136 411-L Med. Alum. 609 406-L Black 1256 465-L Binder 3200 485-L Balancer 3500 (CONTINUED)
	1111121112

Code 507 - Ottawa	Blue (Metallic)
Enamel (181) 52234 AF	
758-5 Drier 742-A Blue Green 19. 721-A Blue 81. 710-A Alum Med. 156. 705-A Black 257. 701-A White 261. 756-A Binder 355.	3 406-L Black 908 5 440-L Violet 1156 5 411-L Mad. Alum. 1280 9 401-L White 1302 6 465-L Binder 3204
Code 508 - Samarra	Beige
Ename 1 (,93) 52304 AH	Lacquer (246) 52304 LH
758-5 Drier 18 717-A Red Oxide 20. 730-A Green Gold 23 732-A Ferrite Yellow 30 705-A Black 67 700-A White 135 756-A Binder 363	5 406-L Black 178 3 453-L Ferrite Yellow 322 9 402-L White 670 8 465-L Binder 1474 9 485-L Balancer 3560
Code 509 - Bengal Br	own (Metallic)
Enamel (181) 6525 AH	Lacquer * (202) 6525 LH
758-5 Drier 749-A Maroon 19 752-A Trans. Oxide 32 718-A Mon Maroon 63 710-A Alum. Med. 193 705-A Black 357	7 430-L Mon Red 60 5 455-L Red Eold 196 8 411-L Alum. Med. 716 9 406-L Black 1332
Code 510 - Hampton	Grey (Metallic)
Enamel (181) 51055 AH	Lacquer * (202) 5/055 LH
758-5 Drier 17 799-A Maroon 20 797-A Mon Red 23 722-A Blue 30 710-A Alum Med. 48 705-A Black 185 701-A White 190 756-A Binder 353	7 406-L Black 1100 10 440-L Violet 1216 10 401-L White 1268 13 411-L Alym Med. 1304 13 465-L Binder 3188 18 485-L Balancer 3488



(CONTINUED)

Code 511 - Balmoral Ereen (Metallic) Enamel Lacquer * (202) 51872 LH No Formula 492-L Blue 28

192-L Blue 28 401-L White 152 406-L Black 575 411-L Alum. Med. 911 425-L Ereen 1287 465-L Binder 3120 485-L Balancer 3520

| 1937-1938 Engine Green |
| NOTE: Scale Settings for Quarts |
"IMRON!" Ename!	"DULUX" Ename!		
559-U Blue	3571/2	VD5450 Drier	45
561-U Green	6171/2	I-D White	105
578-U Fellow	6821/2	15-D Blue	255
536-U Red Oxide	780	46-D Fellow	355
555-U White	8121/2	3-D Iron Blue	955
535-U Black	832		

* * * * *

Lauren also has prepared a little booklet on auto painting techniques and materials. It was done several years ago, and thus some of the products mentioned therein have been reformulated or superseded; however, for conciseness, readability, and solid, no-nonsense help, Lauren's booklet can't be beat. Many of us don't have the equipment or skill to paint a car, but I learned long ago that if you understand the materials and processes a professional may use, and can discuss them intelligently with him, you're more likely to get a good job. I had no idea before I read this booklet just how complex a subject auto painting is, and how many different products and procedures go into a first-class paint job. Members may obtain a copy of the booklet, entitled The DuPont System for Antique Automobile Refinishing, by writing to Lauren (see the Roster for address) with SASE [39¢].

While we are on the subject of paint, a few observations of my own may help you.

- People's perceptions of color can vary widely: one man's "light" is another's "medium" and one man's blue another's green.
- The color of any substance is due to the light which falls upon it. Thus, altering the character of that light will alter the color, an elementary principle of physics which finds many applications in photography. If you are looking at color samples to make a choice, do so in natural sunlight. Fluorescent lamps, especially the "cool white" and "warm white" commonly used, can make certain colors look very different. I learned this the hard way.


(CONTINUED)

- The impact of large areas of a color -- a whole car, say -- can be very different from the impact of a small sample of that color. It is therefore important to try to visualize how a color will look on the car in bright sunlight. If in doubt, invest in painting a 4 x 4 sheet of masonite with the color you are considering. You may be surprised, unpleasantly.
- Black is black and white is white, you say? Wrong! Blacks and whites can vary noticeably. (I learned that the hard way, too.) So even if you go for the basic black, make sure it's the same black over the whole car.
- Painting is as much art as it is science, and one man's technique may not suit another, although both get creditable results. Experimentation and practice to make the most of one's own personal talents are necessary. Some people cannot successfully use certain products that others have no trouble with. There is thus no one right way, to the exclusion of all other ways, although plainly there are lots of wrong ways.
- Patience, according to a Chinese proverb, is power. If you're painting, don't rush it.
- Some people use lacquer and enamel on the same car: typically, where this is done the lacquer is put on the outside surfaces and the enamel on door frames and pillars, firewall, etc. If you do this, be sure your enamel matches the final rubbed-out color of your lacquer. There may be a difference, even though the freshly-sprayed look of both is the same. If necessary, make some adjustment to the enamel mix.

My personal feeling -- and I must emphasize the "personal" -- is that it is not necessary to attempt to duplicate the color that was on your car when it was new, or even to duplicate precisely any 1937 or 1938 Buick color, although we are now well on our way to being able to do that. I do not mean to suggest that everyone run amok, or that because your kids' orthodontist (or your lawyer, for that matter) cuts a fancy figure in a metallic gold Seville, you should have a metallic gold '37 Roadmaster. I think most people would agree it's appropriate to stay within the range of what was done originally, just as most people would say you shouldn't paint an 1830 Greek Revival house pink, or even green. But there were in 1937 three blues, two greens, and at least three grays. By 1942 there were five greens and seven grays. So, if you like a particular shade of maroon, or gray, or dark blue, or beige, use it.

Lastly, this: another of my pleas for help. You will have noted from the foregoing that, in making his 1937 formulas, Lauren used a mint set of 1937 large-size color chips, which he was fortunate enough to acquire several years ago. If any member has such a set of 1938 color samples, or knows where one can be bought, borrowed or stolen, please contact the Editor. I have bet myself that one of you can come up with this. Lauren needs this to make the 1938 formulas, and you will win the undying gratitude of many people if you do it.





Our first member in South America: from Cali, COLOMBIA,



Jose Pardo's 1937 model 68



TECHNICAL TIPS



1938 DASHBOARD. Through the courtesy and efforts of Ross McConnell (*485) of Oakville, Ontario, we can take a clearer look at the series 40 dash picture contained in the 1938 sales brochure. You will recall that I tried this in the September issue, but it didn't come out too well, due to the ink used in the original and the limitations of the equipment available to my printer. Ross has a printing business in Toronto, and has access not only to his own facilities, but also to some others in the city where very high quality (and expensive) state-of-the-art printing and photo reproduction work is done. He very kindly offered to do a top-quality "PMT" of the page, using his own copy of the brochure. Remember, this is not a photo of an original car, but an artist's rendition. I believe, however, that it is quite close to the pattern actually used on the 1938 Special.

see opposite page

MORE ON WOODGRAINS. Ross McConnell tells me that McLaughlin-Buicks (or at least some of them) had a different grain pattern than the U.S. product. Ross sent me some photos of the original dash in a Canadian 1938 Special showing a horizontal stripe walnut pattern with a hint of a "mottle" effect: somehwat similar to the 1937 U.S. 40 series dash, and not at all like the 1938 U.S. Specials. Ross also says that in McLaughlin-Buicks the grain pattern was applied with a "wheeling pattern machine" which used a series of rubber pattern wheels running in a paint reservoir. This too is much different from the technique described by Lou Wildt using metal plates (Vol. IV, No. 1, page 19). In restoring his car, Ross did a very creditable imitation of the Canadian original; here is his description of how he did it:

To obtain a grain pattern I used a base coat light tan paint as a ground coat and then applied the wood grain effect using household antiquing Stains - Old Masters Stain - Natural Walnut #K-104. This is a thick pigment that when applied to the finish darkens the base coat. The trick is to remove the excess within seconds with a paper towel made into a ball which when drawn across the stain will streak or grain the finish. The more you draw the towel across the stain the lighter the affect and the more pronounced the grain. Any weekend furniture restorer that has antiqued furniture can do it. I practiced on my window mouldings first as the instrument panel with all it's contours and cut outs is much more difficult and has to be done in sections. After drying, the finish is very dull - but after 7 days curing I top coated with a clear plastic spray which brought up the grain and also protects the finish - simular to varnishing wood.

Total expenditure was about twenty dollars and alot less than the "Professional" - if you can fine one.

Producing the Roadmaster's burled oak/mohogany pattern takes the experience of a wood finisher but they apparently can reproduce the effect if you talk to them nicely and promise them a ride in your jewel.

Thanks, Ross!



TECHNICAL TIPS



JOHN HOPLEY'S RUBBER PARTS. I received a letter from John saying that the response to his offer on rubber parts has been so overwhelming, he has run out of rubber. The original rubber stock John obtained at a very favorable price; as of early November, he had been quoted prices over twice the cost of the original stock. At this price level, John cannot compete with other suppliers. He is looking for other sources, but please, until further notice, no more orders. This is unfortunate, and we are sorry about it, but at least it shows me you guys are reading this stuff.

SIDEMOUNT COVERS: HELP NEEDED. As announced previously, John Hopley is also working on molds to produce sidemount covers in fiberglass for 40 and 60 series cars. My understanding is that each series had a different size cover, and presumably a different size well in the fender. John has a 60-series car with sidemounts, and thus can get the appropriate dimensions from it. However, he does not have the dimensions for 40-series cars. Since there were far fewer 6-wheel Specials sold, it is obvious that this project will be of greatest benefit to Special owners. It is also obvious that, if this project is to succeed, the parts must fit correctly. So, I need a volunteer to provide the exact dimensions of 40-series sidemount covers. As many measurements as reasonably possible, but at least outside diameter and width at the widest point. In addition, John will be trying to produce the wells in fiberglass. We also need 40-series dimensions for these: length; width plus depth at center. This is a terrific project. The price of original sidemount fenders and parts has gone through the roof, if you can find them at all. The hardware is available in reproduction, but the covers and wells are not. It is our hope that, when the project is finished, any 40 or 60 series owner will be able to add sidemounts to his car at reasonable cost. PLEASE HELP!

REGULATORS, GENERATORS & STARTERS. Highly recommended by Al Klavora (#498), whose very nice '37 model 47 will get into these pages sooner or later, is a firm in the Cleveland area called RBR ELECTRONICS. They specialize in repair or rebuilding of generators and starters -- 1920's through 1950's vintage -- to original factory specifications or better. In addition, they sell a solid-state voltage regulator claimed to work equally well with 3-brush generators (as found in '37 and '38 Buicks) or the newer 2-brush models. This regulator (called the VR-6) has no moving parts, and performance is said to be improved over the original in several respects. Al has two of them and is very pleased with it; he also is pleased with their generator and starter work. Price of the VR-6 is \$54.95. Call "Ron" at 216/585-7178 or send SASE for info.

RBR ELECTRONICS P.O. Box 5480 Willowick, Ohio 44094.

PARTS CAR WANTED- Arthur Sommers (#464) wants to find a 1938 parts car (preferably 40 series) in New Jersey or vicinity.

ARTHUR SOMMERS- RD 1, 514 S.Herbertsville Rd.

Brick Town, NJ 08723. 201/938-2495





One of the great things about running this Club (if that is what I'm doing) is that I never know what I will find in the mail, or who will call with what interesting news. I had a call the other night from Paul Cusano (#052) who, besides being one of several physicians in the Club, has a fine '38 46C and a superb '38 40C. Paul has devoted much effort and thought to Buick restoration and history. From this call I learned much.

Firstly, I had heard differing reports about whether, in swapping rear end gears, one needs to change the carrier assembly along with the ring and pinion. In last month's article, I came down on the side of changing the carrier assembly, since this seemed to be the consensus of what I had read and heard. Well, it seems this is only half right. Paul tells me that is correct for 1937; however, for 1938 40-series cars, the 3.9 ring and pinion may be substituted without changing the carrier assembly, or "case." He ought to know, since he has done it on his 46C without problems. Since the Master Parts Book lists different part numbers for 1938 40 and 60 series carrier assemblies, as is the case for 1937, I assumed the '38 60-series gears would not work with the 40-series case.

Paul also had some other interesting and useful observations. He believes that some or all of the noise people may associate with the 4.4 rear end does not come from the drive train, even though it may sound that way. Bob Pipkin has advised us that many engine rebuilders fit pistons too tight in the Buick "straight eight" [see Vol. III, No. 5, page 11]: a clearance of as much as .004 gives good results with "after market" pistons. Paul says a too-tight engine can make a lot of noise and will be very stiff until it is broken in, and break-in can take several thousand miles. He also told me that he knows of several instances in which Specials with the 4.4 ratio have easily and smoothly topped 80 mph and maintained that speed with no trouble. To do this, however, the engine must be well broken-in, have proper balance, and be in perfect tune. It is not realistic to expect an impaired engine to perform like that: 85 mph means 4400 rpm!

Paul also confirmed that 1938 "Self-Shifter" Buicks had two different rear end ratios: the 3.9 gears of the Centuries and "high-speed" Specials, and a special 3.6 gear set. The latter would be found mostly on early production. Apparently, even with the four speeds in the "Self-Shifter" there were complaints from owners living in hilly country that the lower ratio did not give adequate performance, and the 3.9 gear set was made standard sometime in the model year. Paul also told me about a manual-transmission Special he has seen that had the 3.6 rear end as original equipment. (Presumably a special order to the factory.) If the semiautomatic, with a slightly lower

(CONTINUED)

first gear than the manual (3.16 versus 2.94), could not perform well with a 3.6 rear end, it must have really been something to get that car started uphill. The owner, however, claimed it performed fine.

Lastly, Paul suggests -- and I certainly agree -- that Special owners contemplating a "swap" consider their local terrain (hilly or flat), the extent to which they plan to carry four or five passengers plus gear, and the weight of their model car. Obviously, the hillier and heavier, the more likely the "swap" may present driveability problems. There is a difference of some 320 pounds between a '38 Special business coupe (the lightest body) and a convertible sedan (the heaviest).


Many thanks to Paul Cusano for sharing his knowledge and experience with us.



Dug's Doodles



With this issue, we are inaugurating a new feature called "Dug's Doodles." As most of you know, Dug Waggoner (#010), from San Francisco, does advertising design and illustration, and is responsible for our TORQUE TUBE masthead, the Club decal, and other artwork that I use. When he sent in his renewal form, Dug was in a playful mood, and wrote that he could do "drawing stuff." To prove that, he included a little sketch of a "4 x 4." "More of this!" was my reply. The results were amazing: a whole portfolio of 1938 Buicks of marvelous design. According to Dug, when the moon is full these things just "fall out of the pen." He hastens to add that they are done "out of love, not malice," and we hope that none of you will try to put the designs into practice!



1938 Century Droptop ~ Body by LeCocca

QUESTIONS ANSWERED



... by Dave Lewis

MEMBERS PLEASE NOTE: Answers to this month's questions have been "ghost written" by the Editor, after telephone consulation with the Guru (that's Dave). Although this procedure has certain administrative advantages, and all the answers make sense to me, it is just possible that I left something out or otherwise goofed. If anyone takes issue with these (or any other) answers, please let me know. We're trying our darndest to give you practical, informative answers, but we ain't perfect. At least when I write the answers most of the words get spelled right.

Question: I have a question about the rear springs and shocks on my 1938 model $\overline{41}$. The rear seems to be hanging a little low, and when I go over a good-sized bump or railroad tracks the car bottoms out. If I have a few people in the car with me, it really hangs.

- (a) Are there modern replacements for '38 rear shocks that will "bolt in"?
- (b) Is there anything that I can do to better the support action of the rear springs short of taking them out and having them "respring"?
- (c) What about installing air shocks to solve the problem?

Answer: Just in case any new members are not familiar with the differences. while 1937 Buicks have leaf springs at the rear and Delco lever-action shock absorbers on all four wheels, 1938's have coil springs and large tube-type shocks on the rear axle. (Buick has had an all-coil suspension ever since.) The function of shock absorbers is just what the name implies: to dampen and control motion and stabilize the ride. Ordinary shocks, whether lever-action or tube, do not and cannot support the weight of the car. It sounds to us as though your rear springs are broken or have lost their resilience. Crawl under your car with a ruler and measure the distance from the top of the spring at the insulator to the bottom; with a full tank of gas this should be 14 inches. If, as we suspect, the distance is an inch or more less, this is a pretty good indication that the springs are bad. There is no way in which a worn-out coil spring can successfully be rejuvenated. The best course would be to replace the springs, either with new ones or a good used set. There are a few suppliers of made-to-order new coil springs for antique cars. Try National Spring Co., 630 Grand Avenue, Spring Valley, CA 92077 (619/697-3544), or Kanter Auto Products, 76 Monroe St., Boonton, NJ 07005 (201/334-9575), or look through the ads in Hemings. If you buy springs, be sure they are for a 40-series sedan; coupes used springs with different specifications. All 1938 springs will physically fit all 1938 cars, but there are several different variations in specification.

Monroe Magnum 60 #6828 will replace 1938 rear shocks with a little trimming of the rubber brushings.

(CONTINUED)

Air shocks or "coil-over" booster shocks would probably compensate sufficiently for the worn springs, if you can find some that will fit. Ask the Monroe supplier for the air or booster shocks that correspond to the Magnum 60 #6828, and for the dimensions. Since these are larger in diameter than regular shocks, there may not be enough clearance, even if you can find some of the right length. We don't know of anyone who has put air shocks in a 1938 Buick, but in theory it should work.

Question: I own a 1937 81-F and I want to re-do the brake system. My questions are as follows:


- (a) Do you have modern numbers for front and rear wheel cylinders (EIS, NAPA, etc.)?
- (b) Do you have modern numbers for front and rear wheel cylinder rebuild kits? I bought some recently but the rubber boots were too small. If I get rebuild kits should there be expanders for the springs?
- (c) Where can I get the short hose that comes off the rear of the master cylinder?
- (d) Do you have a modern number for the master cylinder for this car?

 For members' information, front brake hoses for this car may be replaced with EIS SP-183.

Answer: So far as we know, there are no modern replacement master cylinders or wheel cylinders that will fit any 1937 or 1938 Buick. What you should do is take your existing cylinders, remove all the fittings, rubber parts, pistons, etc., clean them thoroughly, and send them to White Post Restorations to be sleeved with brass. (White Post Restorations, White Post, Virginia 22663, 703/837-1140.) Wheel cylinders cost \$28 each; master cylinders \$42. If your cylinders are really bad, or seized up, you may need to have them run through a "hot tank" and glass bead machine first. Cylinders that are pitted will leak sooner or later; the brass sleeve solves this problem permanently, and White Post does a beautiful job with quick turn-around.

We do not have modern numbers for rebuild kits for 80 or 90 series cars, but if you take your restored cylinders to the biggest NAPA store in your area, we believe you will be able to find kits that will work. You need kits that will fit a 14-inch cylinder (front) and 1 3/16-inch cylinder (rear). A good parts counter man should be able to find kits by dimension as well as by part number. We are not sure what you mean by "expanders" but as a general matter kits don't have anything like that in them.

The short hose that runs from the back of the master cylinder on 80 and 90 series cars is very hard to find. We know of no modern replacement. Can any member help with this? Someone who knows what he's doing and has the right tools could probably improvise something out of modern components. This would be a great project for someone.



(CONTINUED)

Question: Was there originally fender welt in the front fenders of 1937 Specials?

Answer: Yes. The welt runs from the rear of the hood opening back to rear of the fender. There is no welt along the hood opening and the forward part of the fender.

Question: After sitting 10 days or so, it appears that the gas drains from my carburetor resulting in hard starting. What causes this?

Answer: This is a typical problem that every '37 and '38 Buick exhibits to at least some degree, and some cranking is usually necessary even if the carburetor is in good condition. (If you think about it, you will realize that many modern cars do not start up right away after a week or more of idleness, either.) For a discussion of carburetor defects that can cause hard starting, see the Dealer Service Bulletin printed in Vol. III, Issue 7, pages 16-19. (That is a 1938 Bulletin but the principles apply equally to 1937.) You will notice that a drop in the float level of 1/8 inch overnight was considered acceptable. Sometimes with age the float chamber becomes permeable and the gas gradually evaporates right through the casting. This can be cured by applying a sealer to the inside of the chamber, but it is probably better to find a non-leaking carb if you have this problem. You might want to consider having your carburetor rebuilt by one of the Buick carburetor experts (see Vol. III, Issue 7, page 11).

The '37-'38 fuel pumps do not put out a great deal of pressure (series 40: 21/2 to 31/2 lbs.; series 60, 80, 90: 3 to 41/2 lbs.) and must of course move gas all the way from the tank by vacuum when the carburetor gas level is low. Some , people have added electric fuel pumps back by the tank where they are not visible. Six-volt electric pumps are available: Walbro, Dupree, Autopulse are three I have heard about. I am told that the "adjustable pressure" feature on some of these pumps does not amount to much. The electric pumps may be installed in series with the mechanical pump, but if you connect the electric pump directly to the ignition, so that it runs continuously, be careful to select one with low pressure so as not to overpower the gasket in the mechanical pump filter bowl. A better set-up, to my mind, is to wire the electric pump so that it runs directly off the battery and may be turned on and off with its own switch. That way it may be used only to prime the carburetor and shut off before cranking the engine. An electric pump can push gas right through the mechanical pump, and the mechanical pump should be able to suck gas through the valves in the electric pump even when the latter is shut off. (There is also less fire danger with this set-up. I People who have added electric pumps say that they result in much quicker starts. I would add a universal throw-away plastic filter between the tank and the electric pump.

DAVE LEWIS



Detailed Restoration And Parts For All 1937 And 1938 Buick Automobiles

3825 South Second Street, Springfield, Illinois 62703 217-529-5290



PARTS FOR SALE



FOR SALE

I have obtained a 1937 80C for some critically-needed parts. Once I have removed these, I will sell all or part of the remainder of the car. Parts to be sold will include:

complete top; all four doors;

frame;

many body parts.

It is unlikely that another 80C will be parted out for a long time, if ever. This may be your only chance to get what you need. The parts to be sold are all that is necessary to make a four-door convertible out of a '37 model 81. (Yes, it can be done; free advice on how to do it if you buy the lot.) Because of the substantial investment I have in this car, and the scarcity and desirability of these parts, they will necessarily be expensive. If you are seriously interested, please call or write with SASE.

DAVE LEWIS
3825 South Second Street
Springfield, IL 62703
217/529-5290 (Call between 9AM & 9PM, CST.)

FOR SALE

E.A.DePOULI (#310) 119 Hardenburgh Ave. Demarest, NJ 07627

(2)	Generator, #1101052, NOS in orig.box, does not	
	come with pulley, 30 40 ser	
(3)	Exhaust manifold center section, 37&38 60,80,90	
	ser. New reproduction\$160.00	
(4)	Gasket for above, triangular, between manifold	
	center & heat riser body\$6.00	
(5)	Heater hose bracket. New reproduction\$6.00	
(6)	Condenser, #1869704, NOS, 37&38 all ser\$1.50	
(7)	Wiper motor rebuild parts: #8897-17; #2620; #2617;	
	#76125-J; #2630; #76190-1. 37&38 all\$1.00	each
	Battery box, used but not rotted. 38 40 ser\$40.00	
(9)	Vacuum starter switch #1868512. NOS but out of box	
	for several years. 38 all ser\$5.00	
(10) Marvel carb, 38 40 ser, with heat riser & vacuum	
	switch. Excellent used\$40.00	
PLE	ASE ADD SHIPPING TO ALL PRICES.	

(1) Starter armature, #823881, NOS, 37&38 40 ser.....\$25.00

PARTS FOR SALE

#	Part(s)	Price	
1	N.O.S. AXLES FOR '37 SERIES 40+60 USED AXLES FOR '37 SERIES 40+60 1 USED FRONT DRUM FOR '37 SERIES 60 1 USED REAR DRUM FOR '37 SERIES 60	\$90.00	PAIR
2	USED AXLES FOR '37 SERIES 40+60	\$25.00	FA
3	1 USED FRONT DRUM FOR '37 SERIES 60	\$35.00	LH.
4	1 USED REAR DRUM FOR '37 SERIES 60	\$25.00	
5	1 USED FRONT DRUM FOR '37 SERIES 40	\$30.00	
6	2 USED REAR DRUMS FOR '37 SERIES 40	\$20.00	EA.
7	1 USED FRONT DRUM FOR '37 SERIES 40 2 USED REAR DRUMS FOR '37 SERIES 40 1 SET USED BACKING PLATES FOR '37 SERIES 60	\$50.00	SET
8	1 USED CAM SHAFT FOR '37 SERIES 40	\$25.00	
9	1 USED VALVE COVER FOR '37 SERIES 40	\$35.00	
10	1 SET USED FRONT SPRINGS FOR '37 SERIES 40	\$30.00	
11	N.O.S. U-JOINT FOR '34-'37 SERIES 40	\$40.00	
12	1 USED CAM SHAFT FOR '37 SERIES 40 1 USED VALVE COVER FOR '37 SERIES 40 1 SET USED FRONT SPRINGS FOR '37 SERIES 40 N.O.S. U-JOINT FOR '34-'37 SERIES 40 NEW AFTER MARKET U-JOINT FOR '37 SERIES 60 LEFT HEADLIGHT COMPLETE FOR '37 RIGHT HEADLIGHT WITH RIM ONLY	\$35.00	
13	LEFT HEADLIGHT COMPLETE FOR '37	\$50.00	
14	RIGHT HEADLIGHT WITH RIM ONLY	\$25.00	
16	USED TAIL LIGHTS COMPLETE '37 BUICK USED CLOCK FOR '37 USED AIR FILTER FOR '37 SERIES 40	\$25.00	EA.
17	USED CLOCK FOR '37	\$20.00	
18	USED AIR FILTER FOR '37 SERIES 40	\$25.00	
20	USED STEERING WHEEL LOCK FOR '37	\$25.00	
21	USED FRONT BUMPERS FOR '37+'38 SERIES 40,60	\$35.00	EA.
22	MARVEL CARB. GOOD COND. NO CHOKE FOR '37 SERIES 40	\$50.00	
23	REBUILT FUEL PUMP FOR '37 SERIES 40	\$25.00	
24	OLD REBUILT FUEL PUMPS FOR '37 SERIES 40	\$20.00	EA.
25	38 HEATER + DEFROSTER NEED REPAIR	\$50.00	
20	N.U.S. CLUTCH DISC FOR '37 SERIES 60,80,90	\$40.00	
2/	USED STEERING WHEEL LOCK FOR '37 USED FRONT BUMPERS FOR '37+'38 SERIES 40,60 MARVEL CARB. GOOD COND. NO CHOKE FOR '37 SERIES 40 REBUILT FUEL PUMP FOR '37 SERIES 40 OLD REBUILT FUEL PUMPS FOR '37 SERIES 40 '38 HEATER + DEFROSTER NEED REPAIR N.O.S. CLUTCH DISC FOR '37 SERIES 60,80,90 NEW REBUILT CLUTCH DISC FOR '37 SERIES 40 INEW AFTER MARKET MUFFER FOR '37-'48 BUICK ALL SERIES FRONT BUMPER BADGE FOR '38 BUICK	\$30.00	
20	FRONT BUNDED BARGE FOR '37-'48 BUICK ALL SERIES	\$45.00	
29	FRUNT BUMPER BADGE FOR '38 BUICK	\$75.00	

ALSO HAVE MANY N.O.S. FRONT END PARTS, WHEEL + AXLE + REAR END BEARINGS

FOR SALE BY:

Dick Der Marderosian 125 Strasser Ave. Westwood, MA 02090 617-326-4306 after 7:00 PM E.S.T.

* ADD 10% FOR SHIPPING AND HANDLING *

FOR SALE

37 radio, good working condition with good face and chrome \$225.00

37 carburator-Stromberg AA1 for series 40 engines good condition \$100.00

37 steering wheel core \$35.00

37 hubcaps - 1 with new chrome \$42.00: 2 need chrome each \$15.00

37 license plate holder and light for trunk back \$15.00

I have other parts including a rebuildable starter, generator, shocks, etc.

Please send S.A.S.E for reply or call between 6:00 p.m. and 10:00 p.m CENTRAL TIME or anytime on weekends. Shipping Extra on all parts.

George Peska #68

2010 Prairie Downers Grove, IL 60515 312-964-1613

37 37 37 37	Trunk lid hold open hinge Trunk lid (Sandblasted) Front doors (Sandblasted) Floor board trans. cover Emergence brake handel		Model Specia	41		50.00 5.00 5.00	
37	Jump seats	(Limite	be)	50.00	set
38 38 38	Glove box door Firewall vent Emergence brake handel Rear fender oblong gravel gaurd					5.00 5.00 5.00	
38 38 38	Dash ash trays Ring that holds the horn botton in Rechromed bumper gaurd					10.00 5.00 25.00	вет
38	Running board brakets (Special) or	(Centur	У)	20.00	set
38 38 38	Brake & clutch pedal (N.O.R.S) Front cowl that holds the grill Floor board trans. cover	(((Centur Centur Centur	У)))	20.00 40.00 5.00	set
38 38 38	Rear bumper (Special) or Rear bumper brakets (Special) or Right side tail light	((Centur Centur No Ler	У)	30.00	set
38 38 38	Right side tail light base Dome light with lens Dome light lens only One parking light base					2.00 10.00 5.00 2.00	set
38 38 38	License plate light lens & cover Headlights complete, except lenses Trunk hinge					5.00 85.00 5.00	set
38	Transmission to a big engine					85.00	
38	Front & rear drums, (2 is a set) (dmaste			40.00	
38	Side panels (No louvers) (dmaste			20.00	
38			dmaste		N.	35.00	
38	Side panels (No louvers)		mited	3		20.00	
38	Front & rear drums (2 is a set) (mited	5		40.00	
38			imited)		20.00	
38	Jump seats (T.5	imited)		50.00	set

All prices plus shipping charges Phone number (301)-551-7236 David A. Bylsma #117 7747 Siden Drive Hanover, Maryland 21076

Fenders: 1937-38 Buick Model 40 left and right front, excellent used, no rust out, both with inner fenders and fender brace, one with parking light base. \$175.00 each. FOB Stan Brown's, Inc., Box 381, Hampton, NH 03842 603-926-2337 lays, 603-926-5136 evenings.

FOR SALE

1938 Buick radio complete with knobs. Was rebuilt but needs minor repair. \$175 US plus shipping.

LLOYD BOTHAM (#387)
Box 911
Almonte, Ontario KOA 1AO
CANADA
613/256-1188

FOR SALE - Please note: Prices do not include shipping .

Sidemount cover for Drivers Side(not tread but sidewall piece) for '37 or '38 Buicks with 16" wheels-Not Century \$35.00	
Wheel Trim Ring for 16" wheel	
Spark Plug Cover for Special Series	
Wheels for '38 Special: total of four(4) with only one	
of these rims in very good condition \$140.00	
Carburetor(STROMBERG) and complete throttle linkage	
for '37 Century: rebuilt and painted EXCHANGE *	*
** exchange for complete '38 Century version-	
THANK YOU	

Paul B. Culp #508 R. R. #2, Box 411 Perkasie, Penna. 18944 215 - 249 - 3166

Please inquire with S. A. S. E.



PARTS WANTED



WANTED

Trunk hinges for 1937 model 81.
Mint or excellent only. Will
pay top price for the right pair.

DAVE LEWIS 3825 South Second Street Springfield, IL 62703 217/529-5290

WANTED

For 1937 model 67-Parking lamp covers. All stainless side molding pieces. Complete air cleaner.

ROBERT SANZOTERA (#556) ABCL Jubail Box R APO New York 09616-5379

WANTED

For 1937 80 series-I need the short hose that connects to the rear of the master cylinder. These are hard to find--can you help?

TOM GENTILE (#130) 26 Wilkenda Ave. Waterbury, CT 06708

WANTED

1938 DeLuxe Grille Guard.

J.A.HAGGLAND (#299) P.O.Box 118 Maitland 7405 Cape., REP.of SOUTH AFRICA

Support Our ADVERTISERS

Antique Cars and Parts Upholstery - Interiors Rubber - Decals - Hardware



Bob's Automobilia

RD 2, Box 137 Annandale, New Jersey 08801 201-236-2403

NOW AVAILABLE:

1937-1938

HOOD ORNAMENTS
HUB CAPS
ENGINE PAINT
FABRICS
GOOD ADVICE
PROMPT SERVICE
SYMPATHY (UPON REQUEST)

. KING PINS . TIMING CHAIN 90 SERIES 60-70-80-90 SER.

EXHAUST MANIFOLD CENTER SECTION 60-80-90 SERIES.

RUNNING BOARD RADIO ANTENNA INSULATOR ASSEMBLIES, ALL NEW REPRODUCTIONS

CLUTCH & BRAKE PEDAL PADS, BLACK OR BROWN, 40-60 SERIES

"CM" SCRIPT, LOCKING GAS CAP, CHROME "PEEP" SIDE VIEW MIRRORS, AUTHENTIC

SCRIPT, FACTORY ACCESSORY, VENT DRIP MOULD MOUNT, \$25/EACH- LEFT OR RIGHT.

ADD 10% SHIPPING EACH ORDER.

\$70/SET

\$45

\$160

\$25/PAIR

\$10/PAIR

\$30.

\$50/PAIR



1927 TO 1953

WIRING HARNESSES

MANUFACTURED WITH THE FINEST MATERIALS AVAILABLE. THE MOST AUTHENTIC REPRODUCTION OF G.M.: WIRE, CONSTRUCTION, AND BRAIDING. ALL WITH COMPLETE INSTALLATION LISTING. WE HAVE SPECIFICATIONS FOR MOST BUICKS, BUT WE CAN MAKE ANY HARNESS THRU 1954 WITH YOUR ORIGINAL SAMPLE. CUSTOM TURN SIGNALS, OPTIONS UPON REQUEST.

ALSO WE HAVE WIRING SUPPLIES AND A BRAIDING SERVICE. CATALOG-INFORMATION: \$2.00




BOX 435 WAYNE, PA. 19087

STEERING WHEELS

Beautifully recast to your orig. center.

Mold and color from N.O.S.

Center Plastic also available.



Send \$2.00,

brochure and color print to: (please state year)

J.B. Donaldson Co. 701 N. 22nd Ave. Phoenix, Arizona 85009

(602) 257-0521



CLUB ROSTER - Part 1

Through the efforts and the kindness of Mike Vosganian (#447) of Woodland Hills, California (and, I believe, of Mrs. Vosganian also) here is the first Club Roster in two or three years. You will note it is arranged alphabetically by name, with supplemental lists by state and by year and model. It is as complete and accurate as we could make it, but there are necessarily a few deficiencies. These deficiencies are due primarily to: (1) the failure of some members to list on the application or renewal form the model numbers of their cars (instead, for example, of "41" they wrote "40 series" or "sedan" or "Special" or nothing); (2) other similar lacks of information; (3) the failure of some members to write legibly; or (4) the failure of a few dozen members to fill out the form at all, despite being asked at least twice to do so. Except for members who joined recently and too late for inclusion if your name is not in the Roster it is because you did not take the trouble to fill out the Application. Don't complain, because I will ignore your complaints.

Part 1 of the Roster, an alphabetical list of the members, appears in this issue. Part 2, lists by state and by year and model car or cars owned, will appear in Issue 4. There was just not enough space to do it all at once in a readable type size. If we've made any mistakes, please contact Mike.

NOTE: An asterisk (*) means unspecified, or a lack of information, or, when used with condition, a car undergoing restoration or a predicted future condition.

Ackerman, Calvin #032 90 Meadow View Ln. Williamsville, NY 14221 (716) 634-4793 home (716) 631-7156 work 1937-665-3

Adler, Mike #104 7 Gettusburg Dr. Englishtown, NJ 07726 (201) 536-1478 home (212) 558-1395 work 1937-41-9

Alderisio, Robert #157 21 Denver Dr. New York City, NY 10956 (914) 634-1829 home 1937-41-8

Allen, Gene #165 1011 University Helena, MT 59601 (406) 443-6475 home (406) 444-2602 Work 1937-46-#

Anderson, Karl F. #847 RT 2 Box 174E Berryville, VA 22611 (703) 955-1026 home 1937-460-5

Arbini, Joe #359 111 Ward Ln. Stamford, CT. 06907 (203) 322-7540 home (203) 324-3766 Work 1937-460-8 1938-460-7

Armstrong, Don #205 103 Ferguson St. Kemptville, Ontario, Canada K0G1J0 (613) 258-3013 home 1938-4419-8

Ash, Chuck #500 305 9th St NE Oelwein, IR 50662 (319) 283-1642 home 1938-41-#

Backer, Curt #463 R 3 Bon 135 Basles, MN 56621 (218) 694-2388 home 1937-41-5

Barton, Jerry 0. #281 24013 SE 416 Enumclaw, WA 38022 (206) 825-5230 home 1937-460-# 1937-46-5

Bea91e: John #278 GPO Box 3466 Sydney, NW Australia 2001 Wadsworth, IL 60093 (02) 929-7773 home (312) 244-7151 home 1938-41-8 (312) 937-5246 work

Beaman, Joseph #262 308 Garrison Dr. Albemarle, NC 28001 (704) 982-6092 home 1937-41-7

Bellon, Dave #002 39-23 27 St. Long Island City, NY 11101 Almonte, Ontario, Canada (718) 786-8973 home (718) 786-8977 work 1937-47-19

Bennett, Guy #161 300 Granger Rd. Wayland, NY 14572 (716) 728-2690 home (716) 728-2260 wark 1937-460-10 1937-44-2 1937-47-3

Berdan, Bob #368 7390 SW 167th Pl. Aloha, OR 97007

Betka, Harold #414 14440 Jody Ln. 1938-41-#

Bieber, Joe #431 26078 Merrill St. Elk, IN 46514 (219) 264-0457 home 1937-41-8

Botham, Lloyd #387 KORIRO (613) 256-1188 home (613) 560-5502 work 1938-460-8

Bowerman, Joyce #531 168 W. Adams Rd. R#4 Bronson, MI 49028 (517) 238-4066 home 1938-465-5

Boyd, Bert #420 16 Woodland Pl. Fort Smith, AR 72984 (501) 782-5226 home 1938-40*-8 1938-90*-8 1938-41-5

Burnett, Conrad P. #434 Chuppa, John #196 150 Commerce Park Dr. 510 Lost Rore Ln. 8943 Falls Ln. Dayton OH 45404 (513) 233-4911 work (703) 430-0389 home 1938-465-8 1937-41-9 (703) 478-0900 Work

(505) 662-5376 home (505) 667-2315 work

Byerley, O. E. #518 1616 Landa St. Los Angeles, CA 98026 (213) 662-8789 home 1937-47-7

Bylama: David A. #117 7747 Sidem Dr. Hanover, MD 21076 (301) 551-7236 home 1938-660-5

Calvert, Ed #454 8844 Ardendale San Gabriel, CA 91775 (818) 286-3053 home (312) 862-(818) 579-4395 work 1933-41-8 1938-44-5

CamPbell, James Jr. #134 7520 Beluga Cir. 12188 Forest Meadows Dr. Anchorage, AK 99504 Perry, MI 48872 (517) 675-7150 home (313) 236-0337 Mork 1937-41-8 1938-41-8 1938-41-6

Rome, NY 13440 (315) 336-7623 home (315) 793-2304 work 1937-41-1

Culp, Paul B. #508
Cavanau9h, Ray #103 RR #2, Box 411
17608 kin9sburg St. Perkasie, PA 18944
Coburn Rd. Granada Hills, CA 91344 (215) 249-3166 home
(203) 649-0556 home (805) 257-4060 work 1937-68-7 1938-61-3
1937-88*-6

Cooke, Daniel N. #548 Dawson, Russell #504
29 Daventry Ct. 2425 Eaton Ln.
Lynnfield, MR 01948 Orlando, FL 32804
(617) 334-4806 home (305) 341-8466
(617) 245-3011 work 1938-468-*

Conliss, Jack #279 5942 Hersholt Ave. Lakewood, CA 90712 (213) 925-3294 home (213) 269-7391 work 1937-91+ 1937-915-+

Cornwell, Thomas #293 558 Burnham Ave. Calumet City, IL 60409 (312) 868-2734 home (312) 862-3737 work

Coulter, Robert M. #348 (997) 338-4780 home (997) 274-0542 work 1937-46-4

Granford, George #202 7114 Riverdale Rd.

Manchester, CT 86848 (885) 257-4868 work (283) 649-8556 home (1937-91-5 (283) 486-4221 work (1937-91-5 (283) 486-4221 work (1937-80#-6 (283) 2866 Passaic Rve. (283) 748-3216 home (283) 783-1712 work (1937-80#-1 (19

DeClario, Steven 2 Plumtree Ln. Fawcett, John R. #242 Commack, NY 11725 18630 Nadol Dr. Southfield, MI 48075 18163 349-8686 work 1313) 569-7170 home (516) 349-8686 work 1938-41-8

Dennis, H. L. #495 RD #1 B 22. Fleming, OH 45729 (614) 374-6777 home 1937-40*-5

DePouli, Ed ***.

119 Hardenburgh Ave.
Demarest, NJ 97627
(201) 767-3168 home
(201) 628-3468 work
1938-80C-5 1938-81-9 Ferris, Patrick C. #463
39337 Logan Dr.
Fremont, CA 94538
(415) 797-3984 home
1938-41-8

(617) 326-4306 hame (617) 933-9844 work

Doucette, Ed #220 PSC #1 Box 4738 APO SanFrancisco/CR 96286 1938-41%-*

(919) 488-1009 home (919) 864-1082 work 1938-60*-9

Evans, John W. #142 1937-61-*
Cimarosti, Raymond #512 Davies, Dodwell #444 P.O. Box 165
Buteau, Richard M. #015 Warren, MI 43093 Bridgetown, W. Hust. 6255
Evans, John W. #142
Community Motors Inc. P.O. Box 165
Bridgetown, W. Hust. 6255
Bridgetown, W. Hust. 6255
Marmond, LR 70404
(504) 542-0286 home (504) 345-0401 work 1937-81-5 1938-41-9 1938-80*-6

> Farano, Rocky #276 27 Cochrane Ave. Bobbs Ferry, NY 10522 (914) 693-3928 home (914) 943-4550 work 1938-668-8

> (313) 569-7170 home (313) 322-0965 work 1938-61-5 1938-67-5 1938-81-5

Feil. Norman #271 550 West Hall Rd. Merritt Island, FL 32953 (385) 453-4014 hone

Flack: Jim #449 13070 Alta Lane So. Los Altos Hills, CA 94022 (415) 941-0603 home (408) 737-2000 X2448 work 1937-46-7 GaPoff, Dr. Neal #526 Gust, Don #043 4984 Ranch Rd. R1 Box 161 Tiburon, CA 94920 Beecher, IL 60401 (415) 435-0486 home (312) 946-2856 home (415) 435-0486 home (415) 524-2225 work 1937-80 TownCar-8

Geer, Jess #133 RFD Box 85 New Liberty, IA 52762 (319) 843-3375 home 1938-46C-#

Geier, Thomas #185 74-20 46th Ave. Elmhurst, NY 11373 (718) 424-5536 home 1938-40#-5

Gentile, Tom #130 26 Wilkenda Ave. Waterbury, CT 06708 1937-81F-6 1937-41-6

Gerberick, George #136 231 Morris West Covina, CA 91790 (813) 962-7444 home (714) 540-2068 work 1937-66-5

Gilmer, E.S. #472 Box 428 Toccoa, GR 30577 (404) 886-3806 home (404) 886-8447 work 1938-44-#

Giordano, Joe S. #333 131 N. Stewart Rd. Liberty, MO 64068 (816) 781-5570 home 1938-660-7 1938-61-7

Glass, H. J. #111 281 S.Pennsylvania St. Denver, CO 80209 (303) 759-5992 home (303) 744-7240 work 1937-68-3 1938-47-9

Goldblatt, Abe #535 111 Colony Dr. Hampden, MA 01036 (413) 566-5558 home 1938-40C-8

Goodman, James E. #477 10354 Mud Lake Rd. Interlochen, MI 49643 (616) 275-7107 home 1938-40#-7

Gordon, Jonathan #204 1997 Beaver Rd. Sewickley, PA 15143 (412) 741-7333 home 1937-67-8

Greek, David #462 1262 State Ave. Cincinnati, OH 45204 (513) 231-0131 home (513) 921-1075 work 1938-90-7 1938-66S-9

Haas, Frank M. #072 318 E. Jefferson St. Morris, IL 60450 (815) 942-2215 home 1937-41-3

Haggland, James #299 P.O. Box 118 Maitland, RS Africa 7405 (021) 585213 home (021) 537422 work 1938-41-9 1938-46C-5 1938-46S-5

Hair, Jimmie #549 P.O. Box 685 Dalton, GA 30720 (404) 278-6970 home (404) 278-6854 work 1937-41-#

Hall, Jerry #226 192 Acorn Ln. Libertyville, IL 60048 (312) 680-9528 home 1937-68-*

Hamilton, Brian #394 P.O. Box 914 Seahurst, WA 98062 (206) 242-2868 home 1938-41-8

Harris, James B. #213 2808 25th St. Lubbock, TX 79410 (806) 797-6377 home (806) 797-4861 work 1938-41-5

Hoffman, Clarence #546 3015 Chatham Cleveland, OH 44113 (216) 281-8343 home 1938-66S-8

Holl, Don #529 1206 Salisburg Pl. Madison, WI 53711 (608) 271-2624 home 1937-41-5

Hollar, Richard #510 540 North Bend Rd. Baltimore: MD 21229 (301) 747-0561 home (301) 770-4000 work 1938-468-3

Holt, John E. #541 6982 Brayton Ave. Citrus Heights, CA 95621 (916) 966-5032 home 1937-90L-3

Hopley, John #044 512 Roney Rd. Bow, WA 98232 (206) 766-6225 home (206) 676-6200 X280 work Hosanna, William #496 1244 Green St. San Francisco, CA 94109 (415) 776-7275 home (415) 839-4302 work 1933-40*-4

Howell, James D. #537 4430 S. Rachel Ln. New Berlin, WI 53151 (414) 786-1820 home 1937-468-7

Howitt, Robert B. #023 Rt. 4, Box 575 South Boston, VA 24592 (804) 575-7398 home 1937-41-7

Huber, Mortimer #198 404 Vine Ave. Park Ridge, IL 60068 (312) 698-3276 home (312) 236-1600 work 1938-660-19

Huegel, Kenneth #325 11 Albion Ct. Rockland, MA 02370 (617) 878-4980 home (617) 723-0800 X552/553 WC Morrisville, PA 19067 1937-41-#

Jackson, Dennis C. #505 18622 Spaulding Ave. Santa Ama, CA 92705 (714) 997-9758 home 1938-40#-5

Jacobson, Bernard #801 4302 Amherst Ln. Rockford, IL 61109 (815) 398-9375 home (815) 654-1955 work 1938-469-8

Jekofsky, Charles #524 6307 North Capitol St. Washington, D.C. 20011 (202) 829-0471 home (202) 275-2767 work

Jones, Dick & Barb #297 517 Ramona Ave. Monterey Park, CA 91754 (813) 307-8822 home 1937-91-8

Jones, Ralph #216 P.O. Box 75 Rayland, OH 43943 (614) 859-2246 home 1938-41-8

Karpinski, Dr. Arthur #063 511 Nat. Bank of Auburn Bld9. Auburn, NY 13021 (315) 252-6121 home (315) 252-0936 work 1937-41-7

Masakian Jay #026 Carpet Gallery 21 E. Clinton St. Newton, NJ 07860 (201) 383-0814 home (201) 383-5435 work 1938-41-4

KirkPatrick, Raymond #24 3604 Baker St. Collegeville, PA 19426 (215) 539-9547 home (215) 265-2255 work 1938-463-6

Klavora, A.F. #498 7655 Puddingstone Chesterland, OH 44026 (216) 729-0122 home (216) 781-2140 work 1937-47-9

Knoebel, Jonathan #522 6410 Hutton Ave. San Diego, CA 92139 (619) 479-7488 home (619) 233-0195 work 1937-91-5

Kubacki, Dr. Thomas #845 239 Valley Dr. (215) 946-8111 work 1938-61-5

Kuebler, Justa #233 5709 Dunham Downers Grove: IL 60516 (312) 968-0077 home 1937-47-#

Ladderud, Keith #163 29033 220th Pl. S.E. Kent, WA 98042 (206) 886-2798 home (206) 237-0303 work 1937-46-5

Landry, Gerald J. #263 34 Goodhue Ave. Chicopee, MA 01020 (413) 592-5088 home 1938-465-10

Lawson, Ray #016 251 Nottingham Troy, MI 48098 (313) 879-7327 home 1938-90L-10 1938-90L-6

Lee: Jon #274 121 Bath Rd. 121 Bath Md 84111 (207) 442-7819 home (207) 725-8298 work 1933-460-8 1938-46-6 1938-61-3 1937-81-8

Lent: Aubrey #490 139 Bombay Rve. North York, Ontario, Canada MSH1C5 (416) 533-9180 home 1937-4819-6

Lewis, Dave #237 3825 S. Second St. Springfield, IL 62703 (217) 529-5290 work 1937-41-10

Little, Paul #100 Harnesses Unlimited P.O. Box 435 Wayne, PA 19087 (215) 688-3448 work

Lackwood, Robert #184 93 Pearsall Pl. Deer Park, NY 11729 (516) 586-6973 home (516) 293-3830 work 1937-66S-8 1937-61-8 1937-66C-5 1937-90L-8

Long, Dr. Lawrence #011 925 S. Colorado Bl. Denver, CO 80222 (303) 771-3355 home (303) 722-1690 work 1937-66C-W

Lusby, Bob #544 2241 Sylvania Ave. Knoxville, TN (615) 573-8708 home 1938-465-5

MacDonald, Robert #540 163 Main St. Erin, Ontario, Canada NOB1TO (519) 833-9150 home 1938-90-9

Madison, Howard #476 3083 Stadium Ave. Napa, CA 94558 (707) 257-3240 home (707) 646-2522 work 1938-41-4

Mont Mahoney, C. #162 3911 Parkview Dr. Salt Lake City, UT 84124 (801) 277-2859 home (801) 268-4301 work 1938-50*-4

Malone, James E. #467 4554 Oxford Cir. Macon, GR 31210 (912) 474-1894 home (912) 788-8888 work 1937-46-10 1938-460-7

Malone, Russell #396 3445 Capella Ln. Alameda, CA 94501 (415) 521-2970 home 1938-469-2

Mandville, Gary #485 16 Cornwall Hts. St. John's, Nfld., Canada A1E3G7 1938-67-7

3707 W. Aster Dr. Phoenix, AZ 85029 (602) 938-6130 home 1938-460-6

Marshall, Gre9 #148 14161 Riverton Cir. Westminster, CR 92683 (714) 897-4217 home 1937-463-3

Matley, Lauren #049 24015 138th Ave. S.E. Kent, WA 98042 (206) 271-2610 home (206) 246-6600 work 1937-400-10

McCaslin, Lanny #088 8216 Via De Lago Scottsdale, AZ 85258 (602) 991-0161 home 1937-668-5 1937-660-5 1938-47-9

McConnell, Ross #484 151 Walby Dr. Oakville, Ontario, Canada L6L4C9 (416) 827-5160 home (416) 625-5392 work 1933-41-8

McCune, Larry #308 4583 Clubhouse Dr. Lakewood, CA 90712 (213) 420-1209 home

McKeand, James #055 46 Brookdale Ave. Milford, CT 06460 (203) 377-1902 home (203) 934-5288 work 1938-41-8

McKee, Joe #433 712 East 18th St. Cheyenne, WY 82001 (307) 634-6263 home (307) 777-7769 work 1937-41-6

McLaughlin, Daniel #466 6608 Forty Mile Point Rogers City, MI 49779 (517) 734-3312 home (517) 734-3184 work

McMichael, Al #319 424 Temple Ct. Woodbury Hts., NJ 08097 (609) 845-1631 home (609) 365-9781 work 1938-61-7

McRoberts, Eric B. #060 3035 N. Chelton Rd. Moorhead, Harvey #031 Colorado Sprines.CO 80909 332 N. Elizabeth (303) 473-9897 home Lombard, IL 60148 (303) 574-1100 work (312) 627-7972 home 1937-46-7

Marshall, Marion #082 Micheletti, Don #250 2023 Menalto Ave. Menlo Park, CA 94025 (415) 324-0339 home (415) 361-5419 work 1938-46C-# 1938-81-5

> Middleton, Larry #069 8300 Kelly Dr. Mentor, OH 44060

Minwielle, Randall #502 218 Military East Benicia, CA 94510 (707) 745-5176 home 1938-60*-6

MisJuns, O.J. #473 1023 Highland Rd. Newton, PA 18940 (215) 860-8801 home (215) 824-1555 work

Monterman, Richard #486 11111 S. StLawrence Ave. Chicago, IL 60628 (312) 785-9138 home (312) 332-5885 work 1938-41-5

Mont9omery, Ray #081 117 Leonie St. Lafayette, LA 78506 (313) 984-4679 home (313) 981-4080 werk 1938-46-1

Monti, Peter N. #090 55 Fairfield Ave. E. Greenwich, RI 02818 (401) 884-1102 home 1938-40*-8 1937-40*-5

Moody, Ed #316 29 Hazel St. Hollis, NH 03049 (603) 889-4297 home 1938-49#-8

Moore: Daug #158 2335 Sondra Dr. Coquitlam, B.C., Canada V3J6Y4 (604) 461-3593 home (604) 524-5000 work 1938-465-7

Moore; John E. #264 12150 E. 5th St. Tucson; AZ S5748 (602) 298-2715 home (602) 886-6212 work 1937-80C-#

Moorhead, Harvey #031 1938-41-8

Moorman, Patrick #156 10323 W. 93rd Ter. Overland Park, KS 66214 (913) 888-1309 home 1938-41-7

Morris, Jeff #108 5621 Farms Dr. Columbus, OH 43213 (614) 866-2302 home (614) 291-1197 work 1938-41-9 1938-41-1 1938-465-1

Morris, Larry J. #543 4248 Leonard NW Grand Rapids, MI 49504 (616) 453-6325 home (616) 698-9810 work 1937-80*-*

Mosen, Keith A. #516 1104 Oakfield Ct. Roseville, CA 95828 (916) 783-9998 home (916) 485-5211 work 1937-41-*

Mullenix, John E. #436 1212 S. Michigan Ave. Hastings, MI 49058 (616) 945-5807 home 1938-61-9

Natale, Tom #188 205 Banks Run Peachtree City, GA 38269 (404) 487-9583 home (404) 487-7933 work 1938-41-7

Nelson, Doug #051 761 Hylo Rd. Salem, OR 97306 (503) 399-0647 home (503) 364-9857 work 1938-668-10

Nelson, Marshall #370 1559 Commercial S.E. Salem, OR 97302 (503) 378-7593 home 1937-80C-10

O'Connor, James J. #534 560 Overlook Dr. Pittsburgh, PA 15216 (412) 341-0753 home 1937-47-9

O'Leno, Robert #501 2746 Laurel Pass Los Angeles, CA 90046 (213) 654-8436 home (213) 651-5080 Work 1938-41-8

Olson, William E. #427 842 Mission Hills Ln. Worthington, OH 43085 (614) 436-7579 home (614) 687-1440 work 1937-47-7

Parisi/ Matt Sr. #442 Box 5 Underhill Ctr. VT 05490 (802) 899-2214 home 1937-460-9

Parkes, R.E. (Dick) #169 5243 Dallas Dr. Kamloops, B.C., Canada V2C4W4 (604) 573-5740 home (604) 828-3569 work 1938-4419-6

Patterson, Hugh W. #300 611 Locke Ave. Waterloo, IA 50702 (319) 235-6659 home (319) 292-8256 work 1938-41-7

Pavlik, Albert #062 1803 Norton Pl. Steubenville, OH 43952 (614) 282-7197 home (614) 282-9776 work 1938-46-8

Pease, Robert #527 336 Castle Crest Rd. Walnut Creek, CA 94595 (415) 933-5766 home (415) 820-0404 work 1938-41-10 1938-44-8

Peck, Scott #318 1178 Emery St. Salt Lake City, UT 84104 (801) 972-5718 home (801) 972-3354 work 1937-41-8

Peterson, Harold #012 102 Grove Alma, MI 48801 (517) 463-5072 home 1937-665-8

Pipkin, Bob #876 2516 62nd S.E. Salem, OR 97301 (503) 363-4712 home (503) 378-3749 work 1938-67-10

Preslan, Clint #461 17900 Riverside Dr. Lakewood, OH 44107 (216) 226-6517 home 1937-81-9

Ramsby, Ralph M. #212 2024 Andrews St. Rockford, IL 61103 (815) 965-7991 home 1938-41-7

Renie, Maurice #413 5911 Cadillac Dr. Speedway, IN 46224 (317) 244-4978 home 1937-47-4

Reynolds, John #061 21622 Tribune St. Chatsworth, CA 91311 1938-41-9

Rhynard, Marvin L. #327 Schlueter Curt #095 15330 Pinehurst Lansing, MI 48906 (517) 484-5188 home (517) 322-1186 work 1938-61-8

Richter, Brad #421 5616 E. Bobolink Fresno, CA 93727 (209) 255-0121 home (209) 488-3119 work 1937-81-8

Riddick, Raymond #506 38 Prescott Dr. Chelmsford, MA 01863 (617) 251-3444 home (617) 486-2455 work

Roberts, Woodie #346 RT 1 Box 569 Sumiton, AL 35148 (205) 648-5221 home 1938-41-*

Rode, William C. #244 RT 2 Box 10K Espaola, WA 99022 (509) 299-3274 home (509) 458-7396 Work 1938-61-2

Root, Jerry #422 71 S. Pollard Dr. Fulton, NY 13069 (315) 592-4373 hame (315) 349-2804 work 1937-41-8

Ross, Bob #128 12528 Pacino St. Cerritos, CA 90701 (213) 860-5686 home (213) 424-8555 work 1937-47-7

Rossi, Steven #520 37 Pawson Tr. Branford, CT 06405 (203) 481-0533 home (203) 795-5671 Work 1937-41-8

Sauers, John #386 620 Wright Loop Williamstown, NJ 08094 (609) 629-9702 home (302) 328-7548 work (2) 1937-47-586 1937-81-6 1937-81F-8 1937-60C-9

Schaffer, Robert Sr. #533 2530 Poinsettia St. 1219 Orchard Ter. Linden, NJ 07036 (201) 925-3428 home (201) 241-0700 work 1938-41-9

Schick, Bill #102 11 Jackson St. Norwalk, OH 44857 (419) 663-1869 home 1937-41-5

18510 Homewood Ave. Homewood, IL 60430 (312) 798-0663 home (312) 798-2132 work 1937-41-9

Schock, Ken #536 401 Dallas Dr. Campbell, CA 95008 (408) 371-3929 home (408) 867-7820 work 1937-47-8

Schultz, Paul #443 17159 E. Hinsdale Ave. Aurora, CO 30016 (303) 690-1943 home (303) 977-6665 work 1937-46C-#

Schwartz, Steve #170 8621 Beekman Dr. Miramar, FL 33025 (305) 432-3637 home (305) 785-4944 work 1938-90L-5

Scudder, Michael #437 13631 Larwood Ln. Houston, TX 77038 (713) 445-0502 home (713) 229-2923 work 1938-41-8

Seymour, Glenn L. #345 8 Cedar St. Potsdam, NY 13676 (315) 265-6985 home 1938-90L-*

ShePard, Jack #138 105-164 Kenneth St. Duncan, B.C., Canada V9L1N4 (604) 746-4634 work 1937-600-5 1938-460-5

Siatta, Dave #511 2516 N. Lotus Ave. Chicago, IL 60639 (312) 693-3626 home (312) 294-2000 work 1938-660-2

Slasser, Eugene #005 RFD 1 Box 121 Concord, NH 03301 (603) 746-3718 home (603) 224-8321 work 1937-40#-5

Smith, Bryant #419 Santa Ana, CA 92706 (714) 953-1823 home (714) 261-7377 work 1937-46S-8

Smith, Gene H. #092 1160 5th St. Manhattan Beach, CA 90266 (213) 379-2847 home (213) 673-0776 work 1938-46-9

Smith, James B. #465 RT 8 Box 828 Tulsa, OK 74106 (918) 425-6990 home 1937-41-4 1938-41-4

Sommers, Arthur #464 RD-1 Box 514S Herbertsville Rd. Bricktown, NJ 08724 (201) 938-2495 home (201) 477-5979 work 1938-40C-8

Steed, John #132 4082 Rocking Chair Rd. Greenwood, IN 46142 (317) 888-8876 home (317) 265-5017 work 1937-660-3

Stein, Bart #391 Box 268-C Turner Rd. Morrisonville, NY 12962 (518) 643-9586 home 1937-44-5

Stephenson, Lester #019 6158 Sundra Dr. E. Petersburg, PA, 17520 (717) 569-3059 home 1938-46-#

Stipler. Ronald #432 22 W. 115 Southcrest Dr. Downers Grove, IL 60516 (312) 852-6220 home (312) 353-6822 work 1938-660-8

Sutton, Herb #004 350 Mesa Rd. Salinas, CA 93908 (408) 455-1079 home (408) 754-8297 work 1938-46-2

Sybo, Henry #229 4626 Broadale Rd. Cleveland, OH 44109 (216) 661-6866 home (216) 524-8188 work 1937-47-6

Tako, Joseph J. #471 1486 Metzger Rd. Valley City, OH 44280 (216) 225-4207 home (216) 687-1016 work 1937-47-#

Terpeluk, Paul #519 202 Chesapeake Ave. Annapolis, MD 21403 (301) 268-6510 home 1938-41-*

Trombetta, Mike #397 1950 Ala Moana Blvd. Honolulu, HI 96814 (808) 521-6748 work 1937-81F-9 1938-41-6

Tyler, James K. #227 1727 S. Humboldt Denver, CO 80210 (303) 777-6073 home 1937-41-9

Tyson, C. E. Jr. #497 3711 Brandswine Dr. Greensboro, NC 27410 (919) 282-1586 home 1937-41-*

Vaillancourt, Howard #440 145 Williams Dr. Guilford, CT 06437 (203) 457-0262 home 1938-41-7 1938-665-*

VanKoten, Charles W. #388 795 Skyway Rd. San Carlos, CA 94070 (415) 323-2257 home (415) 595-1300 1937-61-5 1937-61-1 1937-80C-*

Vanyek, Raymond H. #173 10521 S. Hawthorne Bl. Inglewood, CA 90304 (714) 531-0141 home (213) 674-6285

Vivian, Bill #174 888 Comal Reef Riviera, AZ 86442 1937-46C-4

Vos9anian, Michael #447 4626 Santa Lucia Dr. Woodland Hills, CA 91364 (818) 887-7167 home (813) 881-6603 work 1938-41-8

Wadlar, Milton #521 1525 UnionPort Rd. Parkchester Bronx, NY 10462 (212) 829-4090 home (212) 294-8503 mork 1938-86*-*

Wassoner, Dus #818 251 Kearny St. #309 San Francisco, CA 94108 (415) 232-8879 home (415) 781-2347 work 1938-44-#

Wall, Edward #547 4282 Country Squire LN. Fairfax, VA 22032 (703) 425-9852 home (202) 343-3981 work 1937-61-7

Wallace, Jim #283 16438 Gilmore St. Van Nuys, CA 91406 (818) 785-7246 home 1937-468-10

Wassall, James W. #446 1404 NW 196 St. Seattle, WA 98177 (206) 546-5527 home (206) 575-5847 Work

Watson, Mel #048 2417 N. Shore Rd. Bellingham, WA 98226 (206) 733-9225 home 1938-665-7

Weatherly, Ron #404 1425 Hale Corcoran, CA 93212 (209) 992-4298 home 1938-468-7

Weinstein, Stephen #532 1222 San Carlos Dr. San Luis ObisPo,CA 93401 (305) 544-1726

Whiting, Mick #381 86 Pailway Ave. 1120 7th Ave. S.W. Garfield, Australia 3814 Puyallup, NA 98371 056-292379 home 056-292274 work 1938-465-9

Wilbrand, Adolph #056 571 Hearst Ave. San Francisco, CA 94112

Wildt, Louis #245 4036 McMann Rd. Cincinnati, OH 45245 (513) 752-1099 home 1938-460-5

Wilson, Gary L. #403 9617 Southwestern B1. Rn9ola, NY 14086 (716) 549-2597 home 1938-40#-8

Wilson, Richard #539 22 Noble St. Delaware, OH 43015 (614) 362-1134 home 1937-61-3

Windt, Alex G. #424 RR 2 Box 18 Osoyoos, B.C. Canada VOH1VO (604) 495-2590 home 1937-40#-8

Wingwood, Curtis #459 10119 Kirwood El Paso, TX 79924 (915) 751-0533 home 1937-90-5

140 Winhoven Dr. Coldwater, MI 49036 (517) 238-2475 home 1938-66C-*

Wolford, Doug #168 (206) 848-1670 home (206) 845-8881 work 1937-41-7

Woodring, John H. #448 162 N. Arcadia Park Lexington, KY 40503 (606) 277-5927 home (606) 233-5242 work 1938-41-10

Woods, Ron #528 68 Gore St. Port MacQuarie, NSW Australia 2444 065-831564 work 1937-60*-*

Woolsey, Jim #545 1219 Roosevelt Escondido, CA 92027 (619) 747-5153 home 1938-69*-*


Yokel, Don #075 100 Farmin9dale Dr. Wexford, PA 15090 (412) 935-1436 home (412) 761-9903 work 1937-46-7

Zimmerman, Martin L. #377 RD 2 Box 180 East Earl, PA 17519 (215) 445-6860 home (717) 354-4261 work 1937-41-9

Zimmerman, Paul #217 1806 N.W. 38 Dr. Winhoven, F.H. (Fizz)#406 Gainesville, FL 32605 (904) 372-1344 home (904) 376-0660 work 1938-40*-5



SPECIAL FEATURE!



Getting Your Car Ready for the Spring Mud Runs